

Summary of experience with LHC and SPS IPM monitors in 2011 & 2012 (& 2013)

Mariusz Sapinski, CERN BE/BI



Proton and Heavy Ion Accelerators



Outlook

- High-brightness beams
- Short description of SPS and LHC IPM
 - -HV
 - Gas injection
 - Magnets
 - Imaging, signal distortion (along the path)
- Hardware failures
- Calibration methods




Beams


- Beams with emittance as small as 0.7 μm·rad (pPb run)
- Typical emittance for high-intensity protons: 1.5 μm·rad
- (designed emittance 3.5 μm·rad)
- Up to 1.7·10¹¹ protons/bunch
- Beam size: at 7 TeV, β=100 m: 100 μm
- 2800 bunches




System: HV cage



System: HV cage + PS + control










System: gas injection

- needed in LHC (normal vacuum 10⁻¹¹ mbar)
- gas injection up to 10⁻⁸ mbar
- PVSS application
- manual control (3-4 steps)









System: magnetic field


- Magnetic field needed to keep minimize beam space charge effect
- 0.2 T magnets originally from ISR, yoke modified to extract light
- Need to exchange power converters on SPS magnets to allow cycling.
- magnets are compensated (ie. 2 magnets/detector/plane in the same circuit)
- length 43 cm
- 20 cm space between poles
- Field quality:




Aimant type IMHH












Signal distortion


Solution: masking at level of image processing









Signal distortion



M. Sapinski, CERN


 electrodes and MCPs are NEG-coated to suppress e-cloud 13








Signal distortion


Solution: use EGP to measure nonuniformity and correct for it.
















Video a

Signal distortion

Solution: image filtering, eg. 2D FFT filters (still being tested)








Hardware failures (other than already mentioned)

- HV ctrl card problem with compatibility with VME (linux CPU)
- 5 CID cameras stopped working, in most cases we suspect that intensifier reached MTTF (tbc by ThermoFischer).
- failures of MCPs
 - "conditioning effect" for MCPs
 - too high input electron current might kill MCP
 - abrupt HV change might kill MCP (and dump the beam!)

Killed MCP: creation a conducting channel through the plate: cannot set HV anymore, cannot amplify the signal.

Fit and amplitude dependence

- ROOT fitting library (the same as for BSRT)
- there is a dependence of measured beam sigma on the signal amplitude
- amplitude feedback is crucial (we do it through camera intensifier gain)
 (changing HV on the MCP in the vacuum is risky)




Calibration from specifications

• Camera pixel size: 11.5 μm * 1.6 (taper)

Optical system magnification: 0.2

Calibration = $92 \mu m/pixel$

Calibration in the lab




The value found: 115 ±3 μm/pixel



Beam-based calibration

- Interpolate beam position from neighbor BPMs.
- Make an orbital bump
- Error on orbit position in BGI location: 100 μm (interpolation error)




Calibration = $95-99 \mu m/pixel$

Installation of BPM close to BGI is foreseen during LS1



Cross-calibration (WS, BSRT)

- Because of old MCPs BGI sensitivity starts where WS cannot measure
- But for ions there was an overlap
- BSRT uses cross-calibration with WS, so calibration with BSRT is of "second order".







Ramp-based calibration

$$\sigma^2_{meas} = \frac{\mathcal{E}\beta(\gamma)}{\gamma} - \sigma_{PSF}^2 + ...$$

Data/B2Vp_FillData20130209C.dat





It is possible to optimize the fitting procedure, but is the quadratic correction enough to correct for all errors, especially the beam space charge?



Conclusions

- 1. LHC IPM deals with beams of unprecedented brightness.
- 2. System was in commissioning for the whole period. Almost not used for operation during Run 1 because of difficulties to calibrate it.
- 3. But a lot of studies were done, a lot of data collected, significant upgrades.
- 4. We suspect that there are strong physical reasons behind calibration issue.
- 5. We think that we need a stronger magnetic field.
- 6. SPS IPM was renovated but noise on video signal was too large for most beams to use it.
- There are some hints on how to reduce it.
- 8. A series of upgrades during LS1 is planned but we are happy to hear your advices.